

C Systems Pvt Ltd	WLL MASTER	Doc. No: CSPL/wllmas/200616
		Date: 20-JUN-2016
	Water Leak Locator Master MODBUS Address Specification	Issue Rev.: 1.01
		Page 1 of 1

Modbus Address:

Description	Address	Function Code	R / W
ZONE STATUS OF MODULE ID FROM 1 TO 32	1001 – 1032 for Module ID 1 - 32	0x03	R
LEAK LOCATION OF MODULE ID FROM 1 TO 32	2001 – 2032 for Module ID 1 - 32	0x03	R

Modbus Values:

Cable Length Not Updated	-	1
Healthy	-	2
Sensor Cable Fault	-	3
Alarm	-	4
Communication Fault	-	5
Leak Location	-	Water leak in Centimetres

Function Code:

0x03	-	Read holding register
R	-	Read only

Number of registers:

32